

Dike and stopbank breaching due to overtopping

By

Ninger Kong

Supervised by

Associate Prof. Asaad Yahia Shamseldin

Prof. Bruce William Melville

Colin Nicholas Whittaker

Contents

Previous

- Background
- Dike failures and reasons
- Parameters in dike erosion
- Previous physical experiments
- Research gap

Current

- Experiment setup
- Experimental groups
- Erosion process
- Flow velocity

Background






Collapse of the water side slope of a stopbank due to scouring, Kōkōhinau Bend, 2004. The storm surge produced by Hurricane Katrina overwhelmed numerous levees and caused failure of levees, New Orleans, 2005.



The reason of dike failures



Department of Civil & Environmental Engineering

THE UNIVERSITY OF

7 EALAND

Parameters in experiments

- Dike (stopbank) dimension (geometric design)
 - Dike (stopbank) shape
 - Dike (stopbank) size
- Material
 - Sediment diameter
 - Non-cohesive and cohesive material
 - Mixed material




Parameters in experiments

- Hydraulic condition
 - Constant upstream water level
 - Constant inflow rate
 - Wave impact
 - Downstream boundary condition
 - ▶ ...
- Compaction
- others


Previous physical experiments Dike

• Experimental setup

THE UNIVERSITY OF




Selamont (2009) Purposecrest shape Eliminate the Eliminate



Previous physical experiments Stopbank

Experimental setup




Weai((200167))

THE UNIVERSITY OF

Purpose: threadewelop measof stop bank breaching Shortcoming: seepatopereffecta ton denotice uthat he load to git of measoning the net

Research gap and our aims




- Measure the flow velocity in the breach
- Find the relationship between varies observations
- Use formula to calculate velocity distribution in the breach
- Study the scale effect on dike erosion

Differences between dike and stopbank

Differences

- Breach evolution
- Breach shape
- Flow velocity in the breach
- . .









Dike experimental setup

Flow meter Camera Pipe Camera 🥎 Ultrasonic sensor ADV 1.2 m Drainage system × 0.1 m 0.35 m 0.58 m 3.85 m 0.45 m 0.57 m 0.6 m

(b) Top view








Experimental groups

hmax=0.8m wmax=0.4m b=1.2m

Test	w(m)	h(m)	Slope	b(m)	d50(mm)	Qi(L/s)
Test 1	0.05	0.1	1:2	0.4	0.85	0.5
Test 2	0.05	0.1	1:2	0.4	0.85	0.8
Test 3	0.05	0.1	1:2	0.4	0.85	1.0
Test 4	0.05	0.1	1:2	0.4	0.85	1.2
Test 5	0.05	0.1	1:2	0.4	0.85	1.6
Test 6	0.05	0.1	1:2	0.4	0.85	2.0






Erosion process




Spatial breach mode (0.5L/s)

Plane breach mode (1.2L/s)










Department of Civil & Environmental Engineering

THE UNIVERSITY OF

AUCKLAND

ZEALAND

Flow velocity field




AUCKLAND N EW ZEALAND



Thanks!



Vertical and horizontal erosion rate



Department of Civil & Environmental Engineering

THE UNIVERSITY OF

7 EALAND