




Tsunami Loading Characteristics on Power Poles

Jonathan Andrew, Charles Tucker and Dr Colin Whittaker

Tsunami Hazard




- Review of Tsunami Hazard in New Zealand (Power, 2013)

Impacts on Utility Poles




Utility poles being reinstated following the 2011 Japan Tsunami



An Analysis of Tsunami Impacts to Lifelines (Horspool & Fraser, 2016)


Objectives



An Analysis of Tsunami Impacts to Lifelines
(Horspool & Fraser, 2016)



<https://www.riskscape.org.nz/>



An Analysis of Tsunami Impacts to Lifelines
(Horspool & Fraser, 2016)

Method and Progress

